


- NOTES:
1. ALL BOLTS SHOWN ARE 1/2"x1" MACHINE BOLTS UNLESS OTHERWISE NOTED.
 2. WHEN NECESSARY TO SPLICE SHEETING ANGLE USED AT RAKE OR CORNERS, SPLICE SHOULD BE MADE AT PURLIN OR GIRT WITH 3" MINIMUM LAP.

 P.O. BOX 130819 • TYLER, TEXAS 75713	ERECTION STANDARDS	DRAWING ES-150
	BEARING FRAME ENDWALL	